Protect Your Investment

HOW TO KEEP YOUR GYM FLOORS WORKING FOR YOU









ACR, Inc.

551 Glenn Avenue Wheeling, Illinois 60090 (866) 645-1165

https://acrrestores.com/ JSchaefer@acrrestores.com Msmolka@acrrestores.com

Kiefer U.S.A.

1225 Tri-State Parkway Suite 510 Gurnee, IL 60031 (224) 643-7108

https://kieferusa.com Jason@kieferusa.com





WHY IS HUMIDITY "SO IMPORTANT?

the expected moisture content of your wood surface regions of the US. Below you can see some charts that show average moisture content in certain You can also see how temperature/humidity % directly affects

or what we would expect as a 1/64" expansion of every single board in your on a condition that caused it to be say, 10%, that is a 2% change in the chart below shipped at 8% moisture content, installed at the same moisture content and took For example, if your maple floor (based on 2.%" standard size) was milled and

This is essentially why a constant environment is so important.

conditions change? What will or may happen when there is too much movement caused by

- -Expansion or contraction of individual boards (Will happen for certain)
- year (potential) -Side bonding if a floor goes from a humid time of the year to a less humid time of
- (potential) -Poly balls if the floor goes from a dry time of year to humid time of year
- with movement -Paint may fracture as the board seams (likely) as it is NOT designed to elongate

All of this is ONLY controlled by the environment the flooring is within

MOISTURE CONTENT OF WOOD AT VARIOUS TEMPERATURE AND RELATIVE HUMIDITY


	100° F	90° F	80° F	70° F	60° F	50° F	40° F	30° F	remperature
5%	1.2	1.2	1.3	1.3	1.3	1.4	1.4	1.4	8
10%	2.3	2.3	2.4	2.5	2.5	2.6	2.6	2.6	
15%	3.3	3.4	3.5	3.5	3.6	3.7	3.7	3.7	
20%	4.2	4.3	4.4	4.5	4.6	4.6	4.6	4.6	
25%	5.0	5.1	5.3	5.4	5.4	5.5	5.5	5.5	
30%	5.8	5.9	6.1	6.2	6.2	6.3	6.3	6.3	100
35%	6.5	6.7	6.8	6.9	7.0	7.1	7.1	7.1	Q
40%	7.2	7.4	7.6	7.7	7.8	7.9	7.9	7.9	
45%	7.9	8.1	8.3	8.5	8.6	8.7	8.7	8.7	
50%	8.7	8.9	9.1	9.2	9.4	9.5	9.5	9.5	8
55%	9.5	9.7	9.9	10.1	10.2	10.4	10.4	10.4	ě
60%	10.3	10.5	10.8	11.0	11.1	11.3	11.3	11.3	Q
65%	11.2	11.5	11.7	12.0	12.1	12.4	12.4	12.4	
70%	12.3	12.6	12.9	13.1	13.3	13.5	13.5	13.5	
75%	13.6	13.9	14.2	14.4	14.6	14.9	14.9	14.9	
80%	15.1	15.4	15.7	16.0	16.2	16.5	16.5	16.5	
85%	17.0	17.3	17.7	17.9	18.2	18.5	18.5	18.5	100
90%	19.5	19.8	20.2	20.5	20.7	21.0	21.0	21.0	Q
95%	22.9	23.3	23.6	23.9	24.1	24.3	24.3	24.3	
98%	25.6	26.0	26.3	26.6	26.8	26.9	26.9	26.9	

Relative Humidity %


Source: USDA Forest Products Laboratory

A Moisture Content	May	May Result in an
Difference of	App	Approximate
1%	1/128"	
2%	1/64"	Scant
3%	1/64"	Full
4%	1/32"	Scant
5%	1/32"	Full
6%	3/64"	Scant
7%	3/64"	Full
8%	1/16"	Scant
9%	1/16"	
10%	1/16"	Full
11%	5/64"	
12%	5/64"	Full
13%	3/32"	
14%	3/32"	Full
15%	7/64"	
16%	7/64"	Full
17%	1/8"	Scant
18%	1/8"	Full
19%	9/64"	Scant
20%	9/64"	Full
21%	5/32"	Scant
22%	5/32"	Full
23%	11/64"	Scant
	11/64"	Full

MOISTURE MAP OF NORTH AMERICA



The numbers on the accompanying map provide examples of how average moisture cotents for interior use of wood products vary from one region to another, and from one season to another within a region. Actual moisure content conditions in any location may differ significantly from these numbers.





scrubbing equipment for your maple floor. The Maple Flooring Manufacturers Association does <u>not</u> recommend the use of automated power

automated power scrubber into your general maintenance program, the Maple Flooring Manufacturers manufacturer, finish manufacturer, and / or sports flooring contractor. Before incorporating the use of an MFMA sports floor contractor and /or MFMA maple manufacturer. The use of a power scrubber may nullify your The use of power scrubbing equipment may void warranties provided by your MFMA maple flooring system Association strongly recommends reviewing your warranty and maintenance documentation provided by your

The use of automated power scrubbing equipment may lead to the following negative effects on your maple floor:

Possible adverse effects on the maple boards and subfloor components:

- Gapping between boards due to excessive expansion followed by shrinkage
- Splintering and Shaling of boards due to repeated wetting via scrubbing
- Tripping hazard of uneven board edges caused by cupping or crowning
- Discoloration of maple flooring

Possible adverse effects on the floor finish and paint:

- Chipping and peeling of paint and finish
- Dull finish appearance
- Slip & Fall Safety due to changes in the coefficient of friction
- Premature finish wear.
- on other floor surfaces Peeling of annual recoat finish resulting from cross-contamination by maintenance products used

Possible Equipment Issues:

- Inadequate water extraction heightens potential for floor damage
- Leaky hoses, fittings, or battery
- Improperly designed or damaged deck heads may damage floors

flooring contractor or MFMA maple flooring manufacturer. and/or manufacturers warranties. Please direct all warranty and maintenance questions to your MFMA sports use of power scrubbers. Therefore, it is critical to verify how the use of power scrubbers may affect installer A significant number of flooring issues found during inspections by MFMA staff have been directly attributed to the

See also: Maintenance Recommendations; Cupping, Crowning, Compression Ridging & Compression Set; and Power Scrubbers and Weight.

© Copyright 2022

Disclaimer: The MFMA provides general information to architects, specifiers and consumers. The MFMA, its members, officers and its disclaim any responsibility whatsoever for the accuracy or applicability of these guidelines under all circumstances and conditions.



Tape on a Maple Floor

MFMA does not recommend the use of masking, theatrical, construction, electrical, duct, adhesive or any other kind of tape to mark temporary court boundaries on the surface of a finished maple floor. It is likely that the tape, additional chipping and peeling of the remaining paint/finish in adjacent areas. have a different coefficient of friction than finishes applied to the maple playing surface, and can impact a when removed, will peel away layers of the floor's surface finish. Most tapes promoted for temporary markings person's ability to start, stop and pivot. Removing the surface paint/finish and exposing the maple can result in

the maple flooring below the temporary markings. In addition, most commonly available tapes contain adhesive resins that can etch or stain the floor finish or even

If you have additional questions, please contact MFMA's Technical Director at 888-480-9138

Revised 12/09

Copyright 2020

Disclaimer: MFMA provides general information to architects, specifiers and consumers. MFMA, its members, officers and agents disclaim any responsibility whatsoever for the accuracy or applicability of these guidelines under all circumstances and conditions.



Weight from Riding Power Scrubbers

total weight of a riding power scrubber may have detrimental effects on your maple floor system. The Maple Flooring Manufacturers Association does not recommend the use of automated power scrubbing equipment for general, daily, or weekly maintenance because the use of power scrubbing equipment may void warranties administered by your MFMA maple flooring system manufacturer and/or sport floor contractor. The

for. Those factors include: Concerns: Riding power scrubbers can weigh in excess of 1,200 lbs. when all of the weight factors are accounted

- Weight of the riding power scrubber
- Weight of a fully loaded reservoir
- Weight of the operator

and you have reached that 1,200 lb. weight. scrubber has a 30-gallon reservoir, that can add 250 lbs. to the equipment. Figure in an average 200 lb. operator Riding power scrubbers can weigh in excess of 750 lbs. One gallon of water weighs 8.35 lbs. If the riding power

lead to surface degradation and/or weaken structural components leading to system failure can have detrimental effects. Excessive loading like those resulting from the use of riding power scrubbers can MFMA maple floor systems function extremely well under normal loads, however on occasion significant loads

maple floor boards, the paint and the gymnasium finish. Solution: Stop using a power scrubber of any kind on your maple floor. Power scrubber use can damage the

Steps for Proper Daily Maintenance:

- Sweep the floor daily with a properly treated dust mop. If the floor is used heavily, sweep it up to three times per day.
- Wipe up spills and any moisture on the floor surface.
- Remove shoe marks using an approved floor cleaner applied with a soft cloth or a dust mop. Contact your floor finish manufacturer for approved cleaning products.

MFMA sport floor contractor and/or MFMA maple manufacturer. Association strongly recommends reviewing your warranty and maintenance information provided to you by your Before incorporating general maintenance procedures for your gym floor, the Maple Flooring Manufacturers

See also: Power Scrubbers, Daily Floor Care, Cupping, Crowning, Compression Ridging & Compression Set

If you have additional questions, please contact MFMA's Technical Director at 888-480-9138

Disclaimer: MFMA provides general information to architects, specifiers, and consumers. MFMA, its members, officers and agents disclaim any responsibility whatsoever for the accuracy or applicability of these guidelines under all circumstances and conditions.

© Copyright 2021



Wood flooring may have different issues that may arise after moisture infiltration has occurred. Examples of moisture infiltration would include roof leaks, large spills, burst pipe, etc. The following is a list of issues that have frequently occurred.

Compression Set and Associated Shrinkage

Moisture infiltration may cause excessive shrinkage gaps between flooring strips that are commonly larger than normal seasonal shrinkage gaps after the wood returns to its normal moisture content range.

Cupping and/or Crowning

from the flooring strips taking in excessive moisture Cupping and/or crowning may take place from moisture infiltration due to expansion pressure

Flooring Issues

- 0 fasteners Moisture infiltration may affect the integrity of the flooring and the deterioration of the flooring
- 0 checks The most common affect on flooring from moisture infiltration is in the form of splits and end

• Finish Issues

finish, game lines and logos Excessive expansion and contraction of the flooring strips may cause bonding issues of the floor

Mold and Dry Rot

- 0 moisture. Mold and dry rot on or below flooring strips may be a symptom of prolonged exposure to
- 0 mold Contact your local health officials for local ordinance on proper procedures when dealing with

Continued Performance

- 0 affected by moisture will perform as originally designed The flooring manufacturer and installing contractor cannot guarantee that floors and floor systems
- 0 uniformity concerns issues, which include, but not limited to, dead spots, fractured or splintering boards, and/or Maple wood floors that have been exposed to moisture infiltration may have ongoing performance

See Also: Catastrophic Moisture, Incidental Moisture, and Common Effects of a Flooded Floor

MFMA's Technical Director at 888/480-9138 If you have experienced moisture infiltration, please contact your MFMA Sport Floor Contractor or contact the

Disclaimer: MFMA provides general information to architects, specifiers and consumers. MFMA, its members, officers and agents disclaim any responsibility whatsoever for the accuracy or applicability of these guidelines under all circumstances and conditions.



Catastrophic Moisture

ground related flooding, ruptured pipes, extensive roof damage, activated fire sprinklers, or other sources Catastrophic moisture is best defined as a substantial influx of free water associated with major sources such as contributing to massive moisture migration.

It is well understood that moisture absorption in wood materials to any degree can result in the issues described herein as adverse concerns. Less well understood, is the detrimental impact that saturated wooden floors, resulting from catastrophic moisture infiltration, can have on the integrity and holding strength of flooring

Fastener Study

Holding Value and Integrity

catastrophic moisture conditions. shows a substantial reduction in fastener holding values when test sections of flooring are subjected to Results of an independent study conducted on behalf of the MFMA (Maple Flooring Manufacturers Association)

strand board and spruce-pine-fir lumber, and industry standard floor fasteners, i.e., staples and cleats. subfloor nailing base consisting of commonly used subfloor materials known to the industry as plywood, oriented Test sections used within this study were comprised of the various combinations of MFMA strip maple flooring, a

Shown below, are the overall results of the various flooring assemblies when they are subjected to catastrophic moisture and dried back to their original wood moisture content. There was an average reduction in fastener holding value of 35.5% after one day of saturation, 38.0% after two days, and 41.5% after 3 days

Whether it be a 1, 2, or a 3-day submersion followed by a drying phase taking each specimen back to their original wood moisture, the range of reduction of fastener holding value is 35-40%. This very substantial reduction in fastener holding value brings into question the long-term integrity and performance of a flooring system

42.0%	38.0%	35.5%
3-Day Saturation	2-Day Saturation	1-Day Saturation
VALUE	AVERAGE LOSS OF FASTENER HOLDING VALUE	AVERAC

Vertical Inter-Gap

underside of the flooring boards and the surface of the subfloor base, creating a condition referred to as 'Vertical surface and subfloor components Inter-Gap' by the scientists conducting this study. According to the same independent study, such spacing measured as much as 0.1" (nearly 1/8") and is considered to be further detrimental to the integration of the floor subfloor. Hence when dried back to their original wood moisture, there is a slight separation gap between the generated by moisture absorption results in the flooring boards expanding differentially with respect to the flooring boards relative to the subfloor material and perhaps slight fastener withdrawal. Expansional force This study of the effects of catastrophic water events also revealed the effect of the expansional forces on the

Conclusion

effects of catastrophic moisture remain hidden after seemingly acceptable aesthetic appearance of the floor saturation does not assure that the floor system will perform as when originally installed. Considerable negative surface is achieved Independent evaluation as described above illustrates that returning to the original wood moisture content after

Potential Adverse Concerns

Compression Set and Associated Shrinkage

content range. Moisture infiltration may cause excessive shrinkage gaps between flooring strips that are larger than normal seasonal shrinkage gaps after the wood returns to its normal moisture

Cupping and/or Crowning

Cupping and/or crowning may take place from moisture infiltration due to expansion pressure from the flooring strips taking in excessive moisture.

Flooring Issues

- fasteners Moisture infiltration may affect the integrity of the flooring and deterioration of the flooring
- The most common effect on flooring from moisture infiltration is in the form of splits and end

Finish Issues

Excessive expansion and contraction of the flooring strips may cause bonding issues of the floor finish, game lines, and logos.

Mold and Dry Rot

Mold and dry rot on or below flooring strips may be a symptom of prolonged exposure to moisture. Contact your local health officials for local ordinance on proper procedures when dealing with mold

Continued Performance

- systems affected by moisture will perform as originally designed. The flooring manufacturer and installing contractor cannot guarantee that floors and floor
- splintering boards, and/or uniformity concerns. Maple wood floors that have been exposed to moisture infiltration may have ongoing performance issues, which include, but are not limited to dead spots, squeaks, fractured or
- to future moisture related issues and/or environmental fluctuations The erosion of fastener holding values and vertical inter-gapping makes a floor more susceptible

Flooded Maple Floor, and Incidental Moisture See also: Cupping, Crowning, Compression Ridging & Compression Set, Dead Spots, Common Side Effects of a

If you have experienced catastrophic moisture infiltration, please contact your MFMA Sport Floor Contractor or contact the MFMA's Technical Director at 888/480-9138

Revised 8/22

© Copyright 2022

Disclaimer: MFMA provides general information to architects, specifiers, and consumers. MFMA, its members, officers and agents disclaim any responsibility whatsoever for the accuracy or applicability of these guidelines under all circumstances and conditions.





WHY IS HUMIDITY "SO IMPORTANT?

the expected moisture content of your wood surface regions of the US. Below you can see some charts that show average moisture content in certain You can also see how temperature/humidity % directly affects

or what we would expect as a 1/64" expansion of every single board in your on a condition that caused it to be say, 10%, that is a 2% change in the chart below shipped at 8% moisture content, installed at the same moisture content and took For example, if your maple floor (based on 2.%" standard size) was milled and

This is essentially why a constant environment is so important.

conditions change? What will or may happen when there is too much movement caused by

- -Expansion or contraction of individual boards (Will happen for certain)
- year (potential) -Side bonding if a floor goes from a humid time of the year to a less humid time of
- (potential) -Poly balls if the floor goes from a dry time of year to humid time of year
- with movement -Paint may fracture as the board seams (likely) as it is NOT designed to elongate

All of this is ONLY controlled by the environment the flooring is within

MOISTURE CONTENT OF WOOD AT VARIOUS TEMPERATURE AND RELATIVE HUMIDITY


	100° F	90° F	80° F	70° F	60° F	50° F	40° F	30° F	remperature
5%	1.2	1.2	1.3	1.3	1.3	1.4	1.4	1.4	8
10%	2.3	2.3	2.4	2.5	2.5	2.6	2.6	2.6	
15%	3.3	3.4	3.5	3.5	3.6	3.7	3.7	3.7	
20%	4.2	4.3	4.4	4.5	4.6	4.6	4.6	4.6	
25%	5.0	5.1	5.3	5.4	5.4	5.5	5.5	5.5	
30%	5.8	5.9	6.1	6.2	6.2	6.3	6.3	6.3	100
35%	6.5	6.7	6.8	6.9	7.0	7.1	7.1	7.1	Q
40%	7.2	7.4	7.6	7.7	7.8	7.9	7.9	7.9	
45%	7.9	8.1	8.3	8.5	8.6	8.7	8.7	8.7	
50%	8.7	8.9	9.1	9.2	9.4	9.5	9.5	9.5	8
55%	9.5	9.7	9.9	10.1	10.2	10.4	10.4	10.4	8
60%	10.3	10.5	10.8	11.0	11.1	11.3	11.3	11.3	Q
65%	11.2	11.5	11.7	12.0	12.1	12.4	12.4	12.4	
70%	12.3	12.6	12.9	13.1	13.3	13.5	13.5	13.5	
75%	13.6	13.9	14.2	14.4	14.6	14.9	14.9	14.9	
80%	15.1	15.4	15.7	16.0	16.2	16.5	16.5	16.5	
85%	17.0	17.3	17.7	17.9	18.2	18.5	18.5	18.5	100
90%	19.5	19.8	20.2	20.5	20.7	21.0	21.0	21.0	Q
95%	22.9	23.3	23.6	23.9	24.1	24.3	24.3	24.3	
98%	25.6	26.0	26.3	26.6	26.8	26.9	26.9	26.9	

Relative Humidity %

Source: USDA Forest Products Laboratory

A Moisture Content	May	May Result in an
Difference of	App	Approximate
1%	1/128"	
2%	1/64"	Scant
3%	1/64"	Full
4%	1/32"	Scant
5%	1/32"	Full
6%	3/64"	Scant
7%	3/64"	Full
8%	1/16"	Scant
9%	1/16"	
10%	1/16"	Full
11%	5/64"	
12%	5/64"	Full
13%	3/32"	
14%	3/32"	Full
15%	7/64"	
16%	7/64"	Full
17%	1/8"	Scant
18%	1/8"	Full
19%	9/64"	Scant
20%	9/64"	Full
21%	5/32"	Scant
22%	5/32"	Full
23%	11/64"	Scant
	11/64"	Full

MOISTURE MAP OF NORTH AMERICA



The numbers on the accompanying map provide examples of how average moisture cotents for interior use of wood products vary from one region to another, and from one season to another within a region. Actual moisure content conditions in any location may differ significantly from these numbers.